

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-035	Smoke	8/18/2008	ADS/TM	S11WW_013MH	Dry	Yes	2,132.22



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-035	Smoke	8/18/2008	ADS/TM	S11WW_013MH	Dry	Yes	2,132.22

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11WW_011G1	S11WW_011MH	S11WW_005MH	275.3482	8
S11WW_013G1	S11WW_013MH	S11UU_010MH	279.8657	8
S11WW_024G1	S11WW_024DE	S11WW_011MH	316.2646	8
S11UU_010G1	S11UU_010MH	S11UU_008MH	324.3995	8
S13YY_011G1	S13YY_011MH	S11WW_001MH	336.2079	8
S11UU_004G1	S11UU_004MH	S11UU_018UN	284.6403	8
S11WW_005G1	S11WW_005MH	S11WW_013MH	36.9546	8
S11WW_012G1	S11WW_012MH	S11UU_004MH	278.5401	8

Observations & Photos

Obs_ID S1028-035-OB01

Address 3613 Dennlyn Road

Status Private

Source Cleanout

Location Yard - front

Nearest MH S13YY_011MH

Comments Smoke from cleanout in front yard. 3613 Dennlyn Rd.



Picture \S1028-035-OB01-P01.jpg

Comments Front of house, 3613 Dennlyn Rd.

Obs_ID S1028-035-OB02

Address 3611 Dennlyn Road


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11WW_001MH

Comments Smoke from cleanout in front yard. 3611 Dennlyn Rd.



Picture \S1028-035-OB02-P01.jpg

Comments Front of house, 3611 Dennlyn Rd.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-035	Smoke	8/18/2008	ADS/TM	S11WW_013MH	Dry	Yes	2,132.22

Obs_ID S1028-035-OB03

Address 3603 Dennlyn Road


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11WW_001MH

Comments Smoke from cleanout in front yard. 3603 Dennlyn Rd.



Picture \S1028-035-OB03-P01.jpg

Comments Front of house, 3603 Dennlyn Rd.

Obs_ID S1028-035-OB05

Address 3509 Dennlyn Road

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11WW_011MH

Comments Smoke from cleanout in front yard. 3509 Dennlyn Rd.



Picture \S1028-035-OB05-P01.jpg

Comments Front of house, 3509 Dennlyn Rd.

Obs_ID S1028-035-OB04

Address 3508 Dennlyn Road

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11WW_011MH

Comments Smoke from cleanout in front yard. 3508 Dennlyn Rd.



Picture \S1028-035-OB04-P01.jpg

Comments Front of house, 3508 Dennlyn Rd.

Obs_ID S1028-035-OB06

Address 3505 Dennlyn Road

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11WW_011MH

Comments Smoke from cleanout in front yard. 3505 Dennlyn Rd.



Picture \S1028-035-OB06-P01.jpg

Comments Front of house, 3505 Dennlyn Rd.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-035	Smoke	8/18/2008	ADS/TM	S11WW_013MH	Dry	Yes	2,132.22

Obs_ID S1028-035-OB07

Address 3415 Dennlyn Road

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11WW_012MH

Comments Smoke from cleanout in front yard. 3415 Dennlyn Rd.



Picture \S1028-035-OB07-P01.jpg

Comments Front yard, 3415 Dennlyn Rd.

Obs_ID S1028-035-OB08

Address 3412 Dennlyn Road

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11WW_012MH

Comments Smoke from cleanout in front yard. 3412 Dennlyn Rd.



Picture \S1028-035-OB08-P01.jpg

Comments Front of house, 3412 Dennlyn Rd.

Obs_ID S1028-035-OB09

Address 3408 Dennlyn Road

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11UU_004MH

Comments Smoke from cleanout in front yard. 3408 Dennlyn Rd.



Picture \S1028-035-OB09-P01.jpg

Comments Front of house, 3408 Dennlyn Rd.

Obs_ID S1028-035-OB10

Address 3400 Dennlyn Road


Status Private

Source Cleanout

Location Yard - front

Nearest MH S11UU_004MH

Comments Smoke from cleanout in front yard. 3400 Dennlyn Rd.



Picture \S1028-035-OB10-P01.jpg

Comments Front of house, 3400 Dennlyn Rd.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-035	Smoke	8/18/2008	ADS/TM	S11WW_013MH	Dry	Yes	2,132.22

Obs_ID S1028-035-OB11

Address 3402 Dennlyn Road

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11UU_004MH

Comments Smoke from cleanout in front yard. 3402 Dennlyn Rd.



Picture \S1028-035-OB11-P01.jpg

Comments Front of house, 3402 Dennlyn Rd.
